

790-44-03L
790-36-03L

Handwritten

USNRC ETC
TELEPHONE REPORT

JUL 30 9:21

FACILITY: Sequoyah 1 and 2 DOCKET #: 50-327
50-328
DATE: 7/27/79 TIME: 4:00 p.m. LIC. OCC. #: SWP-79-S-9

SUBJECT: Potential CDR: Inadequate Design of 3/4" Test Lines on Safety
Injection Header

DESCRIPTION OF OCCURRENCE: Licensee reported that the 3/4" test lines from
the 8" low head safety injection headers as designed do not allow
for acceptable piping flexibility per ANSI B31.7 during particular
transients. The licensee is evaluating this problem for applicability
to Watts Bar Units 1 and 2. If determined reportable a 30-day report
is due 8/27/79

POOR ORIGINAL

M. J. Gouge

SIGNATURE

*Boig
5/1/1*

628 147
7908140 718 S
190404