NHC FUHM 366 U. S. NUCLEAR REGULATORY COMMISSION (7.77) · . A LICENSEE EVENT REPORT CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 0 0 0 0 0 -0 0 3 4 1 2 0 0 3 V S LICENSEE CODE CON'T L 6 0 5 0 0 0 3 3 4 7 0 7 2 4 7 9 8 0 8 0 7 7 9 9 60 61 DOCKET NUMPZR 68 69 EVENT DATE 74 75 REPORT DATE 80 REPORT 0 1 SOURCE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10 During performance of the baseplate inspection procedure developed to comply with IE 0 2 Bulletin 79-02, an inoperable baseplate was observed. The pipe hanger baseplate was 0 3 H-208 which is on the three inch charging line near the regenerative heat exchanger in 0 4 containment. The concrete expansion anchors in the baseplate were improperly installed 0 5 and failed during the pullout test because of oversized holes. 0 6 0 7 9 SYSTEM CAUSE CAUSE COMP VALVE CODE CODE SUBCODE COMPONENT CODE SUBCODE P | C | (11 Z D U P O R T 114 B!(15 Z (16) (12 (13) S 13 18 REVISION SEQUENTIAL OCCURRENCE REPORT EVENT YEAR REPORT NO. CODE TYPE NO LER/RO (17 REPORT 9 21 0 0 TI 0 1 NUMBER COMPONENT MANUFACTURER EFFECT ON PLANT ACTION FUTURE TAKEN ACTION ATTACHMENT SUBMITTED NPRO-4 PRIME COMP METHOD HOURS (22) FORM SUB SUPPLIER Z 9 9 9 26 Z Z (21) 01 0 01 N (23 N (24 (18) (19 (25) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The failure was attributed to the lack of a formal installation procedure uring the 1 0 initial installation. The hanger has been repaired by installing new anchors. 1 A complete report of inspection results and repairs will be made in the response to IE Bulletin 79-02. 3 1 4 80 FACILIT METHOD OF DISCOVERY (30)% POWER OTHER STATUS DISCOVERY DESCRIPTION (32) (29) IE Bulletin 79-02 inspection G (28) 0 0 N/A C (31) 5 44 80 ACTIVITY CONTENT AMOUNT OF ACTIVITY (35 LOCATION OF RELEASE (36) RELEASED OF RELEASE Z 33 Z (34) 6 N/A N/A 10 PERSONNEL EXPOSURES 80 DESCRIPTION (39) NUMBER 0 | (38 N/A 0 30 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 (40 N/A 0 7908140 768 80 LOSS OF CR DAMAGE TO FACILITY (43) TYPE DESCRIPTION Z (42) 9 N/A 80 PUBLICITY NRC USE ONLY DESCRIPTION (45 SUED N (44) N/A 111111 68 6.9 80.3 J. A. Werling 412-643-1258 NAME OF PREPARER _ PHONE .-