

QUALITY ASSURANCE PROGRAM

OF

WELDING INSTITUTE OF ALASKA

(Name of Licensee)

50-17446-01

(License Number)

FOR COMPLIANCE WITH 10 CFR PART 71, APPENDIX E

1. Organization

The final responsibility for the Quality Assurance (QA) Program for Part 71 Requirements rests with Welding Institute of Alaska
(Name of Licensee)

Design and Fabrication shall not be conducted under this QA Program. The QA Program is implemented as shown on the attached organization chart.

The Radiation Safety Officer is responsible for overall administration of the program, training and certification, document control, and auditing.

The Radiographers are responsible for handling, storing, shipping, inspection, test and operating status and record keeping.

2. Quality Assurance Program

The management of Welding Institute of Alaska

(Licensee Name)

establishes and implements this QA Program. Training, prior to engagement, for all QA functions is required according to written procedures. QA Program revisions will be made according to written procedures with management approval. The QA Program will ensure that all defined QA procedures, engineering procedures, and specific provisions of the package design approval are satisfied. The QA Program will emphasize control of the characteristics of the package which are critical to safety.

The Radiation Safety Officer shall assure that all radioactive material shipping packages are designed and manufactured under a QA Program approved by Nuclear Regulatory Commission for all packages designed or fabricated after July 1, 1978. This requirement can be satisfied by receiving a certification to this effect from the manufacturer.

3. Document Control

All documents related to a specific shipping package will be controlled through the use of written procedures. All document changes will be performed according to written procedures approved by management.

The Radiation Safety Officer shall insure that all QA functions are conducted in accordance with the latest applicable changes to these documents.

690257

POOR ORIGINAL


7 908150 333 C

Welding Institute of Alaska

2114 Railroad Avenue
Anchorage, Alaska 99501
(907) 276 3440

*Welding / Quality
Inspection / Integrity*

QUALITY ASSURANCE PROGRAM
ORGANIZATION CHART
FOR
WELDING INSTITUTE OF ALASKA
#50-17446-01
FOR
COMPLIANCE WITH 10 CFR PART 71, APPENDIX E



POOR ORIGINAL

690258



Welding Institute of Alaska

2114 Railroad Avenue
Anchorage, Alaska 99501
(907) 276 3440
Welding / Quality
Inspection / Integrity

QUALITY ASSURANCE PROGRAM

ORGANIZATION CHART (Cont.)

FOR

WELDING INSTITUTE OF ALASKA

#50-17446-01

FOR

COMPLIANCE WITH 10 CFR PART 71, APPENDIX E

DESCRIPTION OF RESPONSIBILITY

1. President, Vice President, Treasurer & Secretary - General management of the company.
2. General Manager - Responsible for operations control of the company, supervision of employees, cost control, job assignments, personnel relations, training.
3. Radiation Safety Officer - Responsible for overall administration of the radiation safety program (including (Quality Assurance), personnel radiation safety training and certification, document control, and auditing of the radiation safety program.
4. Radiographers - Responsible for using, storing, shipping, inspection, testing, operating status, and record keeping of radioisotope sources and devices in accord with written procedures of the company as approved by the Operations Manager and Radiation Safety Officer.

690259

