



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TIC

AUG 8 1979

Docket No. 50-409

Dairyland Power Cooperative
ATTN: Mr. F. W. Linder
General Manager
2615 East Avenue - South
La Crosse, WI 54601

Gentlemen:

The enclosed IE Circular 79-15, is forwarded to you for information. If there are any questions related to your understanding of the suggested actions, please notify NIOSH at the telephone No. listed in the enclosure to the Circular.

Sincerely,

James W. Roy
for James G. Keppler
Director

Enclosures:

1. IE Circular No. 79-15
2. Listing of IE Circulars
Issued in the Last
Six Months

cc w/encl:

Mr. R. E. Shimshak,
Plant Superintendent
Central Files
Director, NRR/DPM
Director, NRR/DOR
PDR
Local PDR
NSIC
TIC
Anthony Roisman, Esq.,
Attorney

646 065

7903170022

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

August 8, 1979

IE Circular No. 79-15

BURSTING OF HIGH PRESSURE HOSE AND MALFUNCTION OF RELIEF VALVE AND "O"-RING
IN CERTAIN SELF-CONTAINED BREATHING APPARATUS

Description of Circumstances:

The Nuclear Regulatory Commission (NRC) has been informed by mailgram (copy enclosed) from the National Institute of Occupational Safety and Health (NIOSH) of occurrences of bursting of the high-pressure hose assembly, and malfunction of the relief valve and of the "O"-Ring in the main line assembly of the SurvivAir Mark I self-contained breathing apparatus. Anyone of these failures would result in immediate loss of air supply to a user.

Licensees who use the SurvivAir Mark I SCBA should:

1. Discontinue use of the apparatus until the units have been inspected by the manufacturer and all necessary repairs or replacements have been made.
2. Contact the manufacturer or supplier of the equipment for instructions on arranging for inspection and repair.

No written response to this circular is required. If you require additional information regarding this subject, please contact the office specified in the enclosed mailgram.

Enclosure:
Mailgram

646 066

DUPLICATE DOCUMENT

Entire document previously entered
into system under:

ANO 790816 0420

No. of pages: 5