



TSC

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

August 8, 1979

Docket Nos. 50-289
50-320

Metropolitan Edison Company
ATTN: Mr. J. G. Herbein
Vice President - Generation
P. O. Box 542
Reading, Pennsylvania 19640

Gentlemen:

The enclosed Circular 79-15, is forwarded to you for information.
If there are any questions related to your understanding of the suggested actions, please notify NIOSH at the telephone No. listed in the attachment to the Circular.

Sincerely,

R. W. McDanahy
for: Boyce H. Grier
Director

Enclosures:

1. IE Circular No. 79-15 w/attachment
2. Listing of IE Circulars
Issued in the Last
Six Months

cc w/encls:

E. G. Wallace, Licensing Manager
J. J. Barton, Project Manager
R. C. Arnold, Vice President - Generation
L. L. Lawyer, Manager - Generation Operations
G. P. Miller, Manager - Generating Station - Nuclear
J. L. Seelinger, Unit 1 Superintendent
W. E. Potts, Unit 1 Superintendent - Technical Support
J. B. Logan, Unit 2 Superintendent
G. A. Kunder, Unit 2 Superintendent - Technical Support
I. R. Finfrock, Jr.
Mr. R. Conrad
G. F. Trowbridge, Esquire
Miss Mary V. Southard, Chairman, Citizens for a Safe Environment

1908230304

646 236

ENCLOSURE 1

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

IE Circular No. 79-15
Date: August 8, 1979
Page 1 of 1

BURSTING OF HIGH PRESSURE HOSE AND MALFUNCTION OF RELIEF VALVE AND "O"-RING IN CERTAIN SELF-CONTAINED BREATHING APPARATUS

Description of Circumstances:

The Nuclear Regulatory Commission (NRC) has been informed by mailgram (copy attached) from the National Institute of Occupational Safety and Health (NIOSH) of occurrences of bursting of the high-pressure hose assembly, and malfunction of the relief valve and of the "O"-Ring in the main line assembly of the SurvivAir Mark I self-contained breathing apparatus. Anyone of these failures would result in immediate loss of air supply to a user.

Licensees who use the SurvivAir Mark I SCBA should:

1. Discontinue use of the apparatus until the units have been inspected by the manufacturer and all necessary repairs or replacements have been made.
2. Contact the manufacturer or supplier of the equipment for instructions on arranging for inspection and repair.

No written response to this circular is required. If you require additional information regarding this subject, please contact the office specified in the attached mailgram.

Attachment:
Mailgram

646 237

DUPLICATE DOCUMENT

Entire document previously entered
into system under:

ANO 7908160420

No. of pages: 5