(3-77)

FORM NA-59! U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

1. LIC	ENGRE		2. REGIONAL OFFICE		
C	noso Coal Develops	ment Co.	U. S. Nuclear Regulatory Commission		
Research Division,			Office of Inspection & Enforcement		
1 1 1 109101			Region I 631 Park Avenu	110	
1 4	bvsvy, reansy	Venia 13/2/	King of Pruss		
3. DOG	KET NUMBER(S)	4. LICENSE NUMBER(S		S. DATE OF INSPECTION	
	30-6081	37-026	94-01	May 30,1979	
The in		litions of your license. The	inspection consisted of sele	radiation safety and (3) compliance with the ective examinations of procedures and repre- of this inspection are as follows:	
	No items of noncompliance or unsafe conditions were found.				
The following items of noncompliance related to records, signs, and labels were found:					
	A. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.4:				
	B. Rooms or at as were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42				
	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)				
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)				
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2) 10 CFR 19				
X					
	G. FormNRC-3 was not properly posted, 10 CFR 20.206(c)				
	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)				
	I. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)				
	J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51				
	K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)				
	L. Records of inventories were not n	naintained. 10 CFR 34.	26	360 109	
	M. Utilization logs were not maintain				
	N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24				
	O. Records of teletherapy electrical interlock tests were not maintained as prescribed in your license.				
P. Other					
Thelip 6. Doman					
7. The NRC Inspector has explained and I understand the items of noncompliance listed above. The items of noncompliance will be corrected within the next 30 days.					
- 3 - 30 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \					
5-30-79) Taul Teller In Try.					
(Date) (Licensee Representative - Title or Position)					