



**Florida  
Power**  
CORPORATION

9 April 1979  
3-0-3-a-2  
CS-79-105

79 APR 11 48:47  
ATLANTA, GEORGIA

Mr. J. P. O'Reilly, Director  
Office of Inspection & Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta St., Suite 3100  
Atlanta, GA 30303

Docket No. 50-302  
License No. DPR-72  
Ref: RII: GTG  
50-302/79-07

Dear Mr. O'Reilly:

We offer the following responses to the apparent Items of Non-compliance in the referenced Inspection Report.

NOTICE OF VIOLATION

As required by Technical Specification 6.8.1.e, concerning implementation of EM Procedure EM-100 as specified in Section 4.3.1.1.f, there should be a portal monitor at the guardhouse (Emergency Assembly Center).

Contrary to the above, on January 22 and 24, 1979, the portal monitor failed to properly operate.

Response: Upon notification of the two cited instances, the portal monitor at the guardhouse was checked for operability and appeared to function properly. This instrument was checked on a subsequent inspection and the inspector did not detect any malfunction of the monitor. We feel no further corrective action is necessary; however, in order to avoid any future noncompliance of this type, the requirement for a portal monitor at the guardhouse will be deleted from the Emergency Plan EM-100. Chem/Rad technicians, properly trained, will be utilized to clear evacuated personnel prior to their release from the plant site. All procedural changes will be implemented prior to 1 May 1979.

Should there be further questions, please contact us.

Very truly yours,

FLORIDA POWER CORPORATION

*W. P. Stewart*

W. P. Stewart  
Director, Power Production

*SPB*  
Nuclear Plant Manager

JC/rc

360 146  
790201  
7907130499 0