



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

TERA
TERA

June 22, 1979


Docket No. 30-04576

Technical Operations Incorporated
Northwest Industrial Park
Burlington, Massachusetts 01803

Gentlemen:

The enclosed Circular 79-09, is forwarded to you for information. If there are any questions related to your understanding of the suggested actions, please notify the contact listed in the attachment to the circular.

Sincerely,


Boyce H. Grier
Director

Enclosure:

1. IE Circular No. 79-09
2. List of IE Circulars Issued
in 1979

7

361 245

7907240 130

ENCLOSURE 1

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D. C. 20555

IE Circular No. 79-09
Date: June 22, 1979
Page 1 of 1

OCCURRENCES OF SPLIT OR PUNCTURED REGULATOR DIAPHRAGMS IN CERTAIN SELF-CONTAINED BREATHING APPARATUS

Description of Circumstances:

The Nuclear Regulatory Commission (NRC) has been informed by mailgram (copy enclosed) from the National Institute of Occupational Safety and Health (NIOSH) of the high rate of regulator diaphragm failures in the Scott Air Pak II/IIA and Presur-Pak II/IIA self-contained breathing apparatus. The failures, ranging from pin holes in the diaphragm to complete diaphragm rupture, have been identified in about 10 percent of the units by the NIOSH field survey. Tests of the Scott apparatus by NIOSH showed reduced respiratory protection in the Demand-Mode and a loss of service time (but no loss of protection) in the Pressure Demand-Mode.

Notice to Licensees:

Many major licensees use the types of Scott apparatus described above. Users of the devices should take the following action:

1. Establish a program for examination of the described respiratory devices in accordance with the attached NIOSH mailgram; or
2. Incorporate the provisions of the NIOSH mailgram into your current program for inspection of the described devices.

No written response to this Circular is required. If you require additional information regarding this subject, please contact the individual specified in the attached mailgram.

Attachment:
MAILGRAM

DUPLICATE DOCUMENT

Entire document previously entered into system under:

ANO 7906290237

No. of pages: 6

361 246