

License No. 40-02331-05

Notice of Violation

Based on the results of the NRC inspection conducted on March 21, 1979, certain activities appear to be in noncompliance with NRC regulations and the conditions of your NRC License No. 40-02331-05 as indicated below:

1. License Condition 14 requires in part that byproduct material be used in accordance with statements and representations contained in letter dated July 19, 1974. Specifically, item 10 of the letter stated that at yearly intervals the instrument is returned to the manufacturer for calibration and service.

Contrary to this requirement, the Nuclear-Chicago Model 2612 survey instrument used to survey rooms in which licensed material was used during the period March 25, 1976 to March 21, 1979 was last calibrated March 25, 1975.

This is an infraction.

2. 10 CFR 20.401(b) requires in part that records showing the results of surveys required by 10 CFR 20.201(b) shall be maintained.

Contrary to this requirement, records of the radiation surveys purportedly performed monthly (when licensed material was used in the Biology Department) to demonstrate compliance with 10 CFR 20.105, permissible levels of radiation in unrestricted areas were not maintained on March 21, 1979.

This is a deficiency.

361 197

7907240509