



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

May 23, 1979

License Nos. 11-12896 ~?
11-12896-0.


Northern Testing Laboratories, Inc.
ATTN: Mr. Richard T. Kanemasu
President
370 Benjamin Lane
Boise, Idaho 83707

Gentlemen:

Thank you for your letter of May 8, 1979, in response to our letter dated April 11, 1979, and the attached Notices of Violation. As a result of our review, we find that additional information, as discussed with Mr. Richard T. Kanemasu by telephone on May 18, 1979, is needed. Specifically, we need a three-part reply, as delineated in the fifth paragraph of our April 11, 1979, letter that directly addresses each of the items listed in our Notices of Violation. You should, therefore, submit this information within ten (10) days of your receipt of this letter so that we can continue our review of this matter.

Should you have any questions concerning this letter, please let me know.

Sincerely,


Glen D. Brown, Chief
Fuel Facility and Material
Safety Branch

~~446-006~~

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

POOR ORIGINAL

7907260119

489 105