

APPENDIX A

NOTICE OF VIOLATION

Basin Surveys, Incorporated

License No. 47-09453-01

Based on the NRC inspection May 16, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by 10 CFR 20.105(b)(2), no licensee shall possess licensed material in such a manner as to create in any unrestricted area from radioactive material in his possession, radiation levels which, if an individual were continuously present in the area, could result in his receiving a dose in excess of 100 millirems in any seven consecutive days.

Contrary to the above, on May 16, 1979, the day of the inspection, radiation levels were measured at the outside of the concrete source storage building of 1.6 mr/hr. These radiation levels were measured with a Victoreen 493 survey meter belonging to Basin Surveys, Inc., last calibrated March 23, 1979.

This is an infraction.

401 286
POOR ORIGINAL
7907260 760