



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

PDR  
CF

JUN 25 1979

Republic Industries, Inc.  
Dor-O-Matic Division  
ATTN: Mr. Loren Slaybaugh  
Vice President,  
Engineering  
7350 W. Wilson Avenue  
Chicago, IL 60656

License No. 12-15641-02E

Gentlemen:

Thank you for your letter dated June 7, 1979, informing us of the steps you have taken to correct the noncompliance identified in our letter dated April 23, 1979. We will examine your corrective action during a future inspection.

With reference to the Immediate Action Letter issued to you, by us, on April 6, 1979, the SD48 Smoke Detector units which you have on hand in locked storage are not to be distributed by Republic Industries Inc., Dor-O-Matic Division, Chicago, Illinois, when Nittan Corporation receives their appropriate licensing. These units cannot be distributed until such time that you can verify by possession of the appropriate documentation, that the SD48 Smoke Detector units on hand have been tested and have passed the inspection program procedures and techniques as prescribed by and specified in the Nittan Corporation license and license application documents.

Your cooperation with us is appreciated.

Sincerely,

A. B. Davis, Chief  
Fuel Facility and  
Materials Safety Branch

cc w/ltr dtd 6/7/79:  
Central Files  
Reproduction Unit NRC 20b  
PDR  
NSIC

489 146

7907300063