SERVICE . CONSULTING . TESTING

## CARROLL ENGINEERS INC.

Tel. (617) 475-7652

200 Andover Street . Box 295 . Ballardvale, Mass. 01810

December 2, 1980

License 20-13042-01

Mr. Boyce H. Grier, Director U. S. Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, Pa. 19406

Subject: I E Bulletin 80-22 Response thereto -

Dear Mr. Grier:

This is written in response to IE Bulletin 80-22, regarding the Automation Industries "quick disconnect" sealed source connectors.

The response to items mentioned follows:

- 1. We have no AI model 200-520-008 or similar assemblies.
- 2. N.A.
- 3. N.A.
- 4. N.A.

5. The emphasis on the need for surveys has been made most recently by reviewing with all radiographic personnel the Case Histories of Radiography Events, published in September, 1980.

Sincerely,

Dy . E. Carroll, Jr. Reliation Safety Officer

CARROLL ENGINEERS, INC.

DECir/bet

CC: Director, Div. Fuel Facil.
Office of Insp.
U. S. NRC, Washington, D.C.