



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

JAN 16 1981

Refinery Products Corporation
ATTN: Mr. Leo J. Warden, R.S.O.
N90 W 14555 Commerce Drive
Menomonee Falls, WI 53051

License No. 48-03665-02

Gentlemen:

This refers to the routine, safety inspection conducted by Dr. W. J. Adam and Mr. J. Mullauer of this office on January 7, 1981, of activities at Refinery Products Corporation authorized by NRC Byproduct Material License No. 48-03665-02 and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letter dated January 31, 1980 regarding apparent items of noncompliance found during our January 8, 1980 inspection. We have no further questions regarding these matters.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix A, and a written response is required.



8102240021

JAN 16 1981

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



W. L. Fisher, Acting Chief
Fuel Facility and Materials
Safety Branch

Enclosures:

1. Appendix A,
Notice of Violation
2. IE Inspection Report
No. 48-03665-02

cc: LFMB, ltr only

cc w/encl:
Central Files
Reproduction Unit NRC 20b
PDR
NSIC