



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

05 DEC 1980

License No. 43-19020-01



Garco Testing Laboratories
Attn: Mr. Rob Duncan, Mgr.
#41 West Central Avenue
Murray, Utah 84107

Gentlemen:

This refers to the routine inspection conducted by Messrs. Jack E. Whitten and C. L. Cain of this office on November 21, 1980, of the activities authorized by NRC Byproduct Material License No. 43-19020-01 and to the discussion of our findings held by the inspectors with members of your staff at the conclusion of the inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements and observations by the inspector.

During this inspection certain of your activities were found not to be conducted in full compliance with NRC requirements. Consequently, you are required to respond to this matter in writing in accordance with the provisions of Section 2.201 of the NRC "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Your response should be based on the specifics contained in the Notice of Violation attached to this letter.

Should you have any questions concerning this letter, please let me know.

Sincerely,

Glen D. Brown, Chief
Fuel Facility and Material
Safety Branch

Enclosure:
Notice of Violation

8102250 491