

~~_____~~
Tels

**n
y
t**
NEW YORK TESTING LABORATORIES, INC.

P. O. BOX 484, 81 URBAN AVENUE, WESTBURY, L.I., N. Y. 11590 • (516) 334-7770 • (212) 297-1449

December 3, 1980

United States Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pa. 19406

Att: Mr. Boyce H. Grier, Director

Subject: IE Bulletin 80-22: Automation Industries, Model 200-520-008
Sealed Source Connectors

Dear Mr. Grier:

We have reviewed the submitted bulletin 80-22 and I.E. circular no. 79-16 with our radiographers.


The importance of following our operating and emergency procedures was emphasized, stressing the importance of radiation surveys in all stages of radiographic work.

Our training and internal audit programs were reviewed to make certain radiographic operations were properly conducted.

Since we do not use Automation Industries equipment, we reviewed possible ways whereby our Technical Operations Inc. equipment could malfunction and again stressed to our personnel the importance of conducting inspection and maintenance of radiographic equipment.

Sincerely,

NEW YORK TESTING LABORATORIES, INC.


Elliot M. Huff
Radiation Safety Officer
Vice President

EMH:ld

8102280151