




UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

The Rupp and Bowman Company
ATTN: Thomas J. Nicholson
Vice President
24505 Indoplex Circle
Farmington Hills, MI 48018



License No. 21-15297-01
License No. 21-15297-02E

Gentlemen:

This refers to the routine safety inspection conducted by Ms. E. Matson of this office on January 16, 1981, of activities at The Rupp and Bowman Company authorized by NRC Byproduct Material Licenses No. 21-15297-01 and No. 21-15297-02E and to the discussion of our findings with you at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix A, and a written response is required.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. L. Fisher

W. L. Fisher, Acting Chief
Fuel Facility and Materials
Safety Branch

Enclosure: Appendix A,
Notice of Violation

cc w/encl:
Central Files
Reproduction Unit NRC 20b
PDR
NSIC

8108230101