SSINS: 6100 TERA

i AUG 10

U.S. NICHAR REGLATORS

DAL 1 0 1981

MEMORANDUM FOR:

Richard E. Cunningham, Director, Division of Fuel Cycle and

Material Safety, NMSS

FROM:

Harold D. Thornburg, Director, Division of Safeguards and

Radiological Safety Inspection, 12

SUBJECT:

REVIEW OF FORMERLY USED SITES

The following information is a summary of IE's efforts to date in response to your June 20, 1980 request regarding the subject.

A temporary instruction was issued in late August 1980 to the regional offices to complete this action by November 1, 1980. Due to restraints on the time of inspectors needed to perform the task, Regions 1 and 3 have not closed out the task to date.

Region I

· License #40-3713 C-4505 - Heppenstall Company, Bridgeport, CT

This site was visited by Region I. No radioactive material was present on site. It is recommended that no further action is required. Inspection Report enclosed.

- License #40-6654 STB-489 IE Dupont, Newport, DE

Region I records indicate that a closeout survey may have been completed and that 20.304 burials may be present on site. A visit will be made to the site when time permits.

- License #40-7004 STB-913 Atlantic Metals Corp., Philadelphia, PA

Region I records show 20.304 burials on site. A visit will be made with time permits.

- License #40-772 STB 424 Bendix Corp., Teterboro, NJ

Region I records show 20.304 burials on site. A visit will be made when time permits.

License #40-943 SMB-135 Wah Chang Corp., Union City, MJ

Region I records and phone conversations indicate that this license covered an operation in Glen Cove, NY. No record could be found of any activity at Union Cit-, NJ. Mg-Th metal clippings were processed. A visit is presently being arranged. There may be 20.304 burials on site. NY State may be involved.

License R-132/c-3623 STA-422 Rare Earths, Inc., Pompton Plains, NJ

Site is division of W. R. Grace. Site visited and found contaminated. AEC released in 1975. Recommend a complete survey, preferably by ORAU.

Region III

- -License #40-501 6-5023 Aluminum Company of America, Cleveland, OH Information to close out this license is enclosed.
- License #40-2274 STB-240 Cleveland Refactory Metals, Cleveland, OH Information to close out this license is enclosed.
- License #40-1790 STB-136 Wellman Dynamics, Bay City, MI
 No information has been found to indicate proper close out. Site visit will be made when time permits.
- License #40-1367 6-5368 Dept. of Army, Granite City, IL.

The Department of the Army is acheduled to perform survey of this site in 1981.

License #40-1363 STB-303 Taylor Forgb and Pipeworks, Gary, IN

No information has been found to indicate proper close out. Site visit planned.

- License #40-481 C-3737 American Bearing Co. Indianapolis, IN

Contacted owners to establish status. Permission was not granted to bisit site. No material is believed on site. Recommend that site not be closed out until positive determination made.

4 1 1

License #40-8015 SUB-996 Corman Industries, Jeffersonville, IN

Telephone contact indicated that material was used for only I week in the 1960's. A closeout survey was made. No site visit planned. Recommend closing out license.

SMB-680 Allis Chalmers, Greendale, WI License #40-2793

No information has been found to indicate proper closeout. Site visit planned.

Little Creek Mining, Marathon Co., WI License #40-2053 R-193

Telephone contact revealed that license was for uranium milling, which was not started. Recommend closeout of license.

Region IV

License #40-1914 R-165 Epsolon Uranium Corp., St. George, V

License was for Vand Th mill, which was not started. Recommend closeout of license.

We are checking regional workloads and priorities and will inform you of the scheduling for the remaining site visits to facilities.

If you have any questions regarding this review, please give me a call.

Harold D. Thornburg Director Division of Safeguards and Radiological Safety Inspection, IE

Enclosure: As stated

CONTACT: D. K. Sly

49-29896

GENEL FCMSS-RSB:18 FCMSS:RSB:II igginbotham