

U.S. NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No. 70-2622/79-01  
70-2584/79-01  
70-2622  
Docket No. 70-2584  
XSNM-1149  
License No. XSNM-1129 Priority K Category 5  
Licensee: Transnuclear, Incorporated  
One North Broadway  
White Plains, New York 10601

Facility Name: N/A

Inspection at: Piketon, Ohio; Dulles International Airport and Enrcute

Inspection conducted: February 26-27, 1979

Inspectors: M. Rogers  
M. Rogers, Physical Security Inspector  
G. Smith  
G. Smith, Auditor

3/27/79  
date signed

3/27/79  
date signed

date signed

Approved by: J. Devlin  
J. Devlin, Chief, Security and Investigation,  
Safeguards Branch

3/13/79  
date signed

Inspection Summary:

Inspection on February 26-27, 1979 (70-2622/79-01; 70-2584/79-01)

Areas Inspected: Announced inspection and surveillance of the security measures afforded an export shipment of SNM. Specific areas included: pre-shipment planning and notification, examination of shipping containers, tamper-safe seals, shipping documents and records, shipment monitoring during transfers, and while in transit, communications tests, and, procedures and instructions to guards and drivers. The inspection involved 52 inspector-hours by 2 NRC inspectors.  
Results: Of the 7 areas examined, no items of noncompliance were identified.

285 231

7907050054