



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

June 26, 1979

2-069-14

Mr. K. V. Seyfrit Director
Office Of Inspection & Enforcement
Region IV
U S. Nuclear Regulatory Commission
611 Ryan Plaza Drive Suite 1000
Arlington, Texas 76012

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Reportable Occurrence Report
Nos. 50-368/79-38 & 50-368/79-39
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.8, we have attached the subject reports concerning the failure of the "A" Steam Generator pressure indicator on the Channel D PPS (50-368/79-38) and the discovery of the Low Pressure Safety Injection Discharge Header Valve being in the closed position (50-368/79-39).

Very truly yours,

David C. Trimble

David C. Trimble
Manager, Licensing

DCT:REI:sh

Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Norman Haller, Director,
Office of Management
Information & Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. W.D. Johnson (ANO)

7907050098