



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TIC

JUN 29 1979

Docket No. 50-409

Dairyland Power Cooperative
ATTN: Mr. F. W. Linder
General Manager
2615 East Avenue - South
La Crosse, WI 54601

Gentlemen:

This refers to the inspection conducted by Mr. L. R. Greger of this office on June 4-7, 1979, of activities at the La Crosse Boiling Water Reactor authorized by NRC Operating License No. DPR-45 and to the discussion of our findings with Mr. R. Shimshak and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix A.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

Based on discussions with your representatives at the site, we understand that: (1) you will complete modifications to the stack particulate and iodine samplers, including installation of an isokinetic splitter, by September 1, 1979; (2) you will collect monthly gas samples from the stack (for one year) to evaluate the accuracy of the gaseous release quantifications derived from the offgas monitors; and (3) you will revise your offgas monitor calibration procedures to include conduct of discrete source linearity checks and implement these changes by the completion of the maintenance outage scheduled for December 1979.

841 170


7908210177

JUN 29 1979

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room, except as follows. If the enclosures contain information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,



for A. B. Davis, Chief
Fuel Facility and
Materials Safety Branch

Enclosures:

1. Appendix A, Notice of Violation
2. IE Inspection Report No. 50-409/79-13

cc w/encls:

Mr. R. E. Shimshak, Plant
Superintendent
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Anthony Roisman, Esq.,
Attorney

841 171