

APPENDIX ANOTICE OF VIOLATION

Babcock and Wilcox Company
Commercial Nuclear Fuel Plant

License No. SNM-1168

Based on the NRC inspection, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by 10 CFR 71.5 and 49 CFR 172.403(c) a radioactive yellow II label must be affixed to each package measuring more than 0.5 millirem per hour but not more than 50 millirem per hour at the external surface of the package.

Contrary to the above, on May 17, 1979 a shipment of UO_2 pellets in a BU-7 container measuring 0.7 millirem per hour was shipped using a radioactive white-I label.

This is a deficiency.

7909040046

960317