

Charles Goodwin, Jr. Assistant Vice President



July 2, 1979

Trojan Nuclear Plant Docket 50-344 License NPF-1

TIC

901308

7909040203

Mr. R. H. Engelken, Director Nuclear Regulatory Commission Region V Suite 202, Walnut Creek Plaza 1990 N. California Blvd. Walnut Creek, CA 94596

Dear Sir:

The following information clarifies our supplementary response of June 25, 1979, to your IE Bulletin 79-06A, Revision 1:

Bulletin Item 2

On Page 2, Section c of the PGE response in the fifth line, the word "relieving" should be replaced by the word "retaining".

Bulletin Item 7.b

On Page 6, the third sentence of the second paragraph of the PGE response should be replaced with the following sentence: "Therefore, Plant procedures have been revised to permit termination of the HPI pumps after 50 degrees subcooling has been achieved (by maintaining RCS pressure above the saturation limit as shown on Figure 3.2, Attachment 2) prior to 20 min only if it has been determined that continued operation would result in an unsafe Plant condition".

Bulletin Item 8

On Page 9, the Auxiliary Feedwater System should be added to the list of ESF Systems that were checked. The FSAR figure reference

121 S.W. Salmon Street, Ponland, Uregon 97204

Portland General Electric Company

Mr. R. H. Engelken July 2, 1979 Page 2

> is Figure 10.4-2. On Page 10, the following sentence should be added to the PGE response: "If the locked valve list is not maintained in Modes 5 and 6, a physical verification of the locked valve positions is performed".

> > Sincerely,

P. Low chining the

C. Goodwin Jr. Assista Vice President Thermal Cont Operation and Maintenance

CG/GAZ/4sb5A29

c: Mr. Lynn Frank, Eirector State of Oregon Department of Energy

> Office of Management Information and Program Control

> > 301309