



Portland General Electric Company

Donald J. Broehl Assistant Vice President

July 31, 1979

Trojan Nuclear Plant  
Docket 50-344  
License NRR-1



Mr. R. H. Engelken, Director  
U.S. Nuclear Regulatory Commission  
Region V  
Suite 202, Walnut Creek Plaza  
1990 N. California Blvd.  
Walnut Creek, CA 94596

Dear Sir:

In our responses to IE Bulletin 79-06A, Revision 1, of April 24, 1979 and June 25, 1979, we committed to provide a description of the design modifications, the necessary operating procedures, and a schedule for implementation of modifications necessary to allow the reactor coolant pumps to continue to operate after SIS and CIS to your office by July 31, 1979 (responses to Items 7.c and 4, respectively).

Subsequently, IE Bulletin 79-06C has been issued and received. In light of the requirements of that Bulletin to immediately trip all reactor coolant pumps following a HPI initiated by low Reactor Coolant System pressure, we have stopped work on the above-mentioned design change, identification of procedures, and associated safety evaluations. Our response to IE Bulletin 79-06C will provide a more accurate description of the method we plan to pursue regarding operation of reactor coolant pumps following a loss of coolant accident. No other response will be forthcoming regarding the above-mentioned modifications to allow reactor coolant pumps to continue operating, as identified in our previous responses to IE Bulletin 79-06A.

Sincerely,

**POOR ORIGINAL**

c: Mr. Lynn Frank, Director  
State of Oregon  
Department of Energy

301310

79-192

7909040 209