

APPENDIX ANOTICE OF VIOLATION

Westinghouse Electric Corporation

License No. SNM-1107

Based on the NRC inspection June 18-22, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by License Condition No. 45, written tests shall be conducted in determining the effectiveness of the training program.

Contrary to the above, the written test was inadequate to determine the effectiveness of the training program in that ten of the twelve questions pertained to respirators and respiratory protection. The other two questions pertained to the hazards associated with breathing air contaminated with uranium and methods to reduce individuals' exposure. The test failed to cover nuclear criticality safety and the various other areas of radiation protection which were covered in the training program.

This is a deficiency.

303032

7909040598

7909040