

APPENDIX A

NOTICE OF VIOLATION

University of Massachusetts Medical School
Worcester, Massachusetts 01605
License No. 20-13758-01

Docket No. 030-01972

Based on the results of an NRC inspection conducted on June 6, 1979, it appears that one of your activities was not conducted in full compliance with NRC regulations as indicated below:

- A. 10 CFR 19.12 requires that you instruct all individuals working in you restricted area in the precautions and procedures to minimize exposure to radioactive materials, in the purpose and functions of protective devices employed, and in the applicable provisions of the Commission's regulations and licenses.

Contrary to this requirement, as of June 6, 1979, you failed to adequately instruct one of your technicians working in a research laboratory in the proper procedures to survey for beta radiation, and another technician in one of your research laboratories in the applicable provisions of the regulations and the conditions of your license.

This is an infraction.

724 116

7909070 294