

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | A | R | A | N | O | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 26 30 37 40 41 42 43 44
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

01 | R | E | P | O | R | T | S | O | U | R | C | E | L | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 8 | 7 | 0 | 8 | 2 | 2 | 7 | 9 | 8 | 0 | 9 | 1 | 2 | 7 | 9 | 9
7 8 60 61 68 69 74 75 80
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | During Mode 1 operation, the data link from CEAC #1 to
 03 | the "B" CPC dropped a bit causing an inaccurate
 04 | output indication, resulting in the "B" CPC channel
 05 | tripping. The data link failed in the conservative direction
 06 | and the remaining CEAC data links were operable.
 07 | There have been no similar occurrences.
 08 | Reportable per T.S.6.9.1.9b.

POOR ORIGINAL

09 | I | A | E | E | I | N | S | T | R | U | Y | Z | 17 | 19 | 0 | 7 | 1 | 5 | 0 | 3 | L | 0 | A | Z | Z | 0 | 0 | 0 | 0 | N | N | S | 5 | 4 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. NUM. CODE VALVE SUBCODE
 LER NO. REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB PRIME COMP SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The data link output error was caused by a failed
 11 | optical amplifier. The data link was repaired and
 12 | the "B" CPC returned to service within one hour
 13 | meeting the requirements of Action Statement
 14 | T.S. Table 3.3-1 Action 2a.

15 | B | 0 | 3 | 0 | Pwr Escalation | A | NA | DISCOVERY DESCRIPTION (32)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY

16 | Z | Z | NA | NA | LOCATION OF RELEASE (36)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY

17 | 0 | 0 | 0 | Z | NA | PERSONNEL EXPOSURES (39)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

18 | 0 | 0 | 0 | NA | PERSONNEL INJURIES (41)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
PERSONNEL INJURIES NUMBER DESCRIPTION

19 | Z | NA | LOSS OF OR DAMAGE TO FACILITY (43)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

20 | N | NA | PUBLICITY ISSUED (45)
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
PUBLICITY ISSUED DESCRIPTION

964361

NAME OF PREPARER: Chris N. Shively PHONE: 501/968-2519

7909180494