

Appendix A

NOTICE OF VIOLATION

Manhattan College Corporation

Docket No. 50-199

Based on the results of an NRC inspection conducted on April 25-26, 1979, it appears that one of your activities was not conducted in full compliance with conditions of your License R-94 as indicated below. This is a deficiency.

Technical Specification E.5, states in part, "Written instructions governing emergency and evacuation procedures shall specify the necessary action to be taken in the event of an emergency, such instructions shall be posted in easily accessible locations both inside and outside the ZFR room."

Contrary to the above the Emergency Procedure was not posted as required on April 25, 1979.

7909250178

OFFICE ▶						
SURNAME ▶						
DATE ▶						