

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [1] [C] [T] [M] [N] [S] [T] [2] [0] [0] [-] [0] [0] [0] [0] [0] [-] [0] [0] [3] [4] [1] [1] [1] [1] [1] [4] [5]

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 33 34 CAE 53 54
CON'T REPORT SOURCE [L] [6] [0] [5] [0] [0] [0] [2] [4] [5] [7] [0] [8] [2] [8] [7] [9] [8] [0] [9] [2] [5] [7] [9] [9]

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[0] [2] On August 28, 1979, at 1045 hours, after venting the pressure suppression chamber,
[0] [3] the vent bypass valve (1-AC-12) failed to close. The required surveillance for
[0] [4] an inoperable containment isolation valve was performed. No consequences, the
[0] [5] downstream valve was closed.
[0] [6]
[0] [7]
[0] [8]

[0] [9] SYSTEM CODE [S] [D] (11) CAUSE CODE [X] (12) CAUSE SUBCODE [Z] (13) COMPONENT CODE [V] [A] [L] [V] [E] [X] (14) COMP. SUBCODE [H] (15) VALVE SUBCODE [D] (16)
LER-RO REPORT NUMBER [7] [9] (17) EVENT YEAR [7] [9] (21) SEQUENTIAL REPORT NO. [0] [2] [8] (24) OCCURRENCE CODE [0] [3] (28) REPORT TYPE [L] (30) REVISION NO. [0] (32)
ACTION TAKEN [Z] (18) FUTURE ACTION [Z] (19) EFFECT ON PLANT [Z] (20) SHUTDOWN METHOD [Z] (21) HOURS [0] [0] [0] [0] (22) ATTACHMENT SUBMITTED [Y] (23) NPRD-4 FORM SUB. [Y] (24) PRIM. COMP. [A] (25) COMPONENT MANUFACTURER [D] [1] [4] [7] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

[1] [0] Disassembly of the main valve revealed rust scale contamination in the area of the pivot
[1] [1] mechanism, apparently sufficient to prevent the valve plug from rotating completely
[1] [2] closed. The valve was cleaned, reassembled and tested. This occurrence is similar
[1] [3] in nature to LER-79-22/3L and 79-23/3L.
[1] [4]

[1] [5] FACILITY STATUS [E] (28) % POWER [1] [0] [0] (29) OTHER STATUS [NA] (30) METHOD OF DISCOVERY [A] (31) DISCOVERY DESCRIPTION [NA] (32)
ACTIVITY CONTENT [Z] (33) AMOUNT OF ACTIVITY [NA] (35) LOCATION OF RELEASE [NA] (36)
PERSONNEL EXPOSURES NUMBER [0] [0] [0] (37) TYPE [] (38) DESCRIPTION [NA] (39)
PERSONNEL INJURIES NUMBER [0] [0] [0] (40) DESCRIPTION [NA] (41)
LOSS OF OR DAMAGE TO FACILITY TYPE [Z] (42) DESCRIPTION [NA] (43)
PUBLICITY ISSUED [Z] (44) DESCRIPTION [NA] (45) 1060 005
7910010415 NRC USE ONLY

Ralph H. Young, Jr.