

Stephen H. Howell Senior Vice President

General Offices: 1945 West Parnall Road, Jackson, Michigan 49201 • (517) 788-0453

September 28, 1979 Howe-254-79

Mr J G Keppler, Regional Director Office of Inspection and Enforcement US Nuclear Regulatory Commission Region III 799 Roosevelt Road Glen Ellyn, IL 60137

MIDLAND NUCLEAR PLANT -UNIT NO 1, DOCKET NO 50-329 UNIT NO 2, DOCKET NO 50-330 CONTAINMENT BUILDING PRESTRESSING TENDONS

Reference: S H Howell letter to J G Keppler; Midland Nuclear Plant; Unit No 1, Docket No 50-329; Unit No 2, Docket No 50-330; Containment Building Prestressing Tendons; Serial Howe-226-79; dated August 23, 1979

The referenced letter was an interim 50.55(e) report, as is this letter, on tendon wires which were in nonconformance to length requirements. The enclosure provides the status of resolution of this condition.

Another report, either interim or final, will be sent on or before October 31, 1979.

WRB/lr

Enclosure: MCAR-33, Interim Report #2, dated September 10, 1979

CC: Director of Office of Inspection and Enforcement Att: Mr Victor Stello, USNRC (15)

Director, Office of Management Information and Program Control, USNRC (1) 1071 165

7910020 498