

POOR ORIGINAL

LICENSEE EVENT REPORT

CONTROL BLOCK 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

01 14 15 25 26 30 31 32
P A T M = 1 00-000000-00 4/1/77 0/1

011 CONT 57 58 59 60 51 62 63 74 75
CATEGORY READ TYPE REPEAT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE
7 8 9 7 8 9 7 8 9 7 8 9 7 8 9 7 8 9

EVENT DESCRIPTION

02 During refueling shutdown while performing the combustion local leak test
03 test the results exceeded the allowable value. The values with the
04 greatest excess were recorded and new values are with better leak
05 tightness are being evaluated. This occurrence is routine (77-06/-)
06

07 8 9 10 11 12 17 43 44 47 48
SYSTEM CODE CAUSE CODE COMPONENT CODE DEVICE EQUIPMENT SUPPLIER COMPONENT MANUFACTURER VIOLATION
X X E - VALVE X

CAUSE DESCRIPTION

08 Several valves do not maintain their leak tightness due to wear
09 metal shavings damaged the seating surfaces on one valve.
10

11 8 9 10 12 13 44 45 46 48
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
A 000 NA A NA

12 8 9 10 11 44 45
FORM OF ACTIVITY RELEASED CONTENT OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
2 0 NA NA

PERSONNEL EXPOSURES

13 8 9 11 12 13
NUMBER TYPE DESCRIPTION
000 2 NA

PERSONNEL INJURIES

14 8 9 11 12
NUMBER DESCRIPTION
000 NA

OFFSITE CONSEQUENCES

15 8 9
NA

LOSS OR DAMAGE TO FACILITY

16 8 9 10
TYPE DESCRIPTION
2 NA

PUBLICITY

17 8 9
Included in weekly news release

ADDITIONAL FACTORS

18 8 9

19 8 9

NAME: W. E. Potts PHONE: 920-2601 (ext 9-114)

1408 244

7910100 505