

POWER & LIGHT PO BOX 6008 . NEW

142 DELARONDE STREET

ANS. LOUISIANA

SEP 12 319

(504) 366-2345

D. L. ASWELL

September 7, 1979 191

LPL 11960 Q-3-A20.03.18 3-A1.01.04

U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Washington, D. C. 20555

ATTENTION: Director, Division of Reactor

Construction Inspection

SUBJECT: Waterford SES Unit 3

Docket No. 50-382 I. E. Bulletin 79-15

Dear Mr. Seyfrit:

We have reviewed the subject bulletin and have found that vertical turbine pumps with impellers located in bowls in a sump or a self contained barrel, are not used on Waterford SES Unit No. 3.

In view of the above, no additional information is provided.

If you have any questions, please advise.

aswell

Yours very truly,

D. L. Aswell

DLA: JFK: smd

cc: Mr. Karl V. Seyfrit, Director Region IV U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

1202 173