



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

August 31, 1979

D. L. ASWELL
Vice President-Power Production

LPL 11905
Q-3-A35.07.07
3-A1.01.04

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3
Docket No. 50-382
Status Report of Significant
Construction Deficiency No. 7
"Loose Control Element Drive
Mechanism Guide Cones"

REFERENCE: LP&L Letter LPL 9582 dated September 12, 1978

Dear Mr. Seyfrit:

In accordance with the requirements of 10CFR50.55(e), the referenced letter submitted an Interim Report of Significant Construction Deficiency No. 7, "Loose Control Element Drive Mechanism Guide Cones." The referenced letter also indicated a planned completion date of September 1, 1979, for corrective action.

Since the issuance of the referenced letter, the work schedule within the Reactor Containment Building has been resequenced. Work is now scheduled to begin on the reactor vessel closure lead during the last quarter of 1979.

The Control Element Drive Mechanism guide cones will be corrected as specified in the interim report during this period. The final report will be forwarded by December 31, 1979.

Yours very truly,

D. L. Aswell

DLA:TFG:smd

1202 285

7910240088

Mr. K. V. Seyfrit

2

August 31, 1979

- cc: 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

1202 286