



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

August 31, 1979

D. L. ASWELL
Vice President-Power Production

LPL 11903
Q-3-A35.07.06
Q-3-A35.07.10
3-A1.01.04

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 75012

SUBJECT: Waterford SES Unit 3
Docket No. 50-382
Status of Significant Construction Deficiencies
No. 6 "Emergency Diesel Generators - Defective Shafts and Springs"
No. 10 "Defective Emergency Generator Roller Pin"

REFERENCE: a) LP&L Letter, LPL 10343 dated December 29, 1978
b) LP&L Letter LPL 10233 dated December 5, 1978
as amended by LPL 10316 dated December 19, 1978

Dear Mr. Seyfrit:

In accordance with the requirements of 10CFR50.55(e), LP&L has previously submitted interim reports of the two Significant Construction Deficiencies concerning the emergency diesel generators. Based on communications with Cooper-Bessemer, the manufacturer of the diesel generators, LP&L reported in the referenced letters that modifications correcting the deficiencies were scheduled to be completed and final reports submitted by August 31, 1979.

Cooper-Bessemer has now informed us that the last of the modification assemblies are now planned for shipment from the factory by September 7, 1979. This delay by Cooper-Bessemer does not adversely impact Waterford 3 construction needs and is acceptable.

Based on the above, we will now submit final reports for Significant Construction Deficiency No. 6 and No. 10 by November 1, 1979.

Yours very truly,

D. L. Aswell

DLA:TFG:smd

1202 287

7910240095

Mr. K. V. Seyfrit

2

August 31, 1979

- cc: 1) Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

1202 288