

Appendix A

SEP 11 1979

NOTICE OF VIOLATION

Consumer Power Company

Docket No. 50-329

Docket No. 50-330

Based on the inspection conducted on August 21-23, 1979, it appears that certain of your activities were not conducted in full compliance with NRC requirements as noted below. This item is an infraction.

10 CFR 50 Appendix B, Criterion XIII requires, in part, to establish measures to control the handling, storage cleaning and preservation of material and equipment in accordance with work and inspection instructions to prevent damage or deterioration.

CPCO procedure FPG-7.000 Revision 0, dated July 1, 1977, Paragraph 7.g established controls to protect material and equipment from activities such as welding.

Contrary to the above, on August 21 and 22, 1979, the inspectors accompanied by licensee representatives observed welding activities in progress at elevation 614' in the auxiliary building, above installed 480V and 4.16KV switchgear with inadequate protection to prevent weld spatter from falling on installed equipment and cables.

1202 350

7910240 175