PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, FA. 19101

(215) 841-4000

September 7, 1979

Mr. Boyce H. Grier, Director Office of Inspection and Enforcement Reg on I United States Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

RE: Peach Bottom Unit No. 3 - Preservice Inspection

REFERENCE: Technical Specification 6.9.3.b, 4.6.G, Table 4.6.1

Dear Mr. Grier:

In accordance with the referenced technical specifications, preservice inspection was completed during the June 2 to June 11, 1979, mini-outage. Enclosed are three copies of the Preservice Inspection Report which summarizes the examinations performed. No reportable indications were observed during this inspection.

This report has been reviewed by the Plant Operation Review Committee, the Philadelphia Electric Company Senior Engineer - Inservice Inspection Section, and the Hartford Steam Boller Authorized Code Inspector. The results of these reviews indicate that the PSI requirements have been met satisfactorily. In addition to the Preservice Inspection Report, a detailed data package has been assembled which supports this examination. This package is retained by Philadelphia Electric Company and is available for your review.

Very truly yours,

Superintendent-Nuclear Generation Division

TCH/cs

Enclosures:

cc: Mr. Julius Claar, Acting Chief Inspector Lepartment of Labor and Industry

1280 193

Mr. Charles E. Berry, Chief Inspector The Hartford Steam Boiler Inspection and Insurance Company

7911010 306 BQ

