

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N E C P R 1 2 0 0 - 0 0 0 0 - 0 0 0 0 3 4 1 1 1 1 4 _____ 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 9 8 7 0 9 1 2 7 9 8 1 0 0 9 7 9 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During steady state operation at 0915 hours, 9-12-79, an indication of possible
0 3 seal failure on "B" reactor recirculation (RR) pump was received. At 1309 hours, a
0 4 high drywell pressure alarm actuated. Power was reduced and "B" RR pump was isola-
0 5 ted at 1331 hours. Investigation indicates an unidentified drywell leak rate in ex-
0 6 cess of 5 gpm (R.T.S. 3.6.C.1) may have occurred in this 22 minute interval. The
0 7 plant was shutdown to replace the "B" RR pump seal. This occurrence had no ad-
0 8 verse affect on the public health and safety. _____ 80

0 9 SYSTEM CODE C B 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE P U M P X X 14 COMP SUBCODE B 15 VALVE SUBCODE Z 16
17 LER/RO REPORT NUMBER 7 9 21 22 EVENT YEAR 23 24 SEQUENTIAL REPORT NO. 0 2 6 27 28 OCCURRENCE CODE 0 3 29 30 REPORT TYPE L 31 32 REVISION NO. 0
ACTION TAKEN A 18 Z 19 FUTURE ACTION Z 20 EFFECT ON PLANT A 20 SHUTDOWN METHOD B 21 HOURS 0 0 6 3 22 ATTACHMENT SUBMITTED N 23 NPRD-4 FORM SUB. 24 PRIME COMP SUPPLIER N 25 COMPONENT MANUFACTURER B 5 8 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The high unidentified drywell leak rate was caused by the failure of the "B" RR
1 1 pump seal at its natural end of life. The seal was replaced with an identical Byron
1 2 Jackson shaft seal. The "A" RR pump seal was replaced in the Spring 1979 refueling
1 3 outage and is operating satisfactorily. No further action is planned. The RR pump
1 4 is a Byron Jackson Type DVSS vertical one stage pump. _____ 80

1 5 FACILITY STATUS E 26 POWER 0 9 8 29 OTHER STATUS NA 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation 32

1 6 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

2 0 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

1271 180

7911060 419

NAME OF PREPARER Richard Flannigan PHONE 402-825-3811