



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

TIC
50-348
364

OCT 19 1979

In Reply Refer To:
RII:JPO
50-348
50-364

Alabama Power Company
Attn: F. L. Clayton, Jr.
Senior Vice President
Post Office Box 2641
Birmingham, Alabama 35291

Gentlemen:

Enclosed is IE Circular No. 79-21, "Prevention of Unplanned Releases of Radioactivity," which provides information in inadvertent releases/on-site spills of radioactivity. Should you have any questions related to the enclosed suggested preventive measures, please contact this office.

Sincerely,

James P. O'Reilly
Director

Enclosures:

1. IE Circular 79-21
2. IE Circulars Issued
in the Last Six Months

1274 254

7911080 277 Q

Alabama Power Company

-2-

cc w/encl:

A. R. Barton
Executive Vice President
Post Office Box 2641
Birmingham, Alabama 35291

J. T. Young
Vice President-Production
Post Office Box 2641
Birmingham, Alabama 35291

C. Biddinger, Jr.
Manager-Corporate Quality Assurance
Post Office Box 2641
Birmingham, Alabama 35291

H. O. Thrash
Manager-Nuclear Generation
Post Office Box 2641
Birmingham, Alabama 35291

H. G. Hairston, III
Plant Manager
Drawer 470
Ashford, Alabama 36312

R. E. Hollands, Jr.
QA Supervisor
Post Office Box U
Ashford, Alabama 36312

1274 255

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

October 19, 1979

IE Circular No. 79-21

PREVENTION OF UNPLANNED RELEASES OF RADIOACTIVITY

Numerous incidents of unplanned releases of radioactivity have been reported to the NRC within the past few months. These incidents of leaks, overflows and spills have resulted in contamination of areas outside of plant buildings. The attached table provides you with summary information on these events, their apparent causes, the radiological consequences and the corrective actions.

We believe that a number of these incidents could have been avoided and preventive actions for these types of unplanned releases should be instituted by all reactor licensees. Based on the reported incidents, the following preventive measures can minimize the occurrence of such events.

1. Review of procedures for transfer of radioactive liquids. Errors in written procedures have led to mistakes in valve line-ups and tank overflows. Written procedures, including check lists for valve line-ups, should be developed and followed for operations which could cause spills of radioactivity. Management controls, including audits, should be employed to assure verbatim compliance with such procedures.
2. Review of "as built" systems having the potential of inadvertent releases because of design or construction errors. Consider items such as:
 - a. Tank overflows should be routed to liquid radwaste tanks.
 - b. Storm drains should be located away from areas with a high potential for spills.
 - c. Consideration should be given to drip pans under equipment, such as pumps and valves, from which leakage is expected.
 - d. Cofferdams should be installed under doors to areas with a potential for radioactive spills.
 - e. Preoperational testing should be conducted that would permit radioactive unit(s) under construction.
3. Periodically functionally test a set of systems that could cause an increase in corrosion degradation have occurred to cause leaks. New permanent:

DUPLICATE DOCUMENT

Entire document previously
entered into system under:

ANO

7908220128

No. of pages: 7

1274 256