

Georgia Power Company
Plant E. I. Ha...
Baxley, Georgia

Reportable Occurrence Report Number 50-321/1979-070

Cause Description and Corrective Actions continued

the design and operating characteristics of the off gas system and have made specific recommendations. A design change request will be initiated in response to these recommendations. The operating procedures and operator training for the equipment are undergoing review and will be revised as necessary.

965 188