

TIC



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

NOV 26 1979

In Reply Refer To:

RIL:JPO


50-302

Florida Power Corporation
Attn: J. A. Hancock, Director
Nuclear Operations
P. O. Box 14042, Mail Stop C-4
St. Petersburg, Florida 33733

Gentlemen:

The enclosed IE Circular 79-23 is forwarded to you for your information.
No written response to this Circular is required. If you have any questions
related to the subject, please contact this office.

Sincerely,


James P. O'Reilly
Director

Enclosures:

1. IE Circular No. 79-23
2. List of Plants That May Have Received
Defective Starter or Contactors
3. List of IE Circulars Issued In
The Last Six Months

1540 189

7912110 143

NOV 26 1979

Florida Power Corporation

-2-

cc w/encl:

G. P. Beatty, Jr.

Nuclear Plant Superintendent

Post Office Box 1240

Crystal River, Florida 32629

1540 190

SSINS: 6830
Accession No.: 7910250496

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

November 26, 1979

IE Circular No. 79-23

MOTOR STARTERS AND CONTACTORS FAILED TO OPERATE

Gould, Inc., Electrical Products Group, reported to the NRC on September 11, 1979 potential defects in certain NEMA size 3, Starters and Contactors. A possible binding or seizure of the carrier assembly, within the support plate of the stationary contact assembly, is caused by an undersized dimension of the support legs.

Starters and contactors with date code 7822 to 7935, model and serial numbers A10, A11, A12, A13, A14, A20, A21, A22, and P10 are involved. Faulty units were manufactured and distributed between June 1, 1978 and August 30, 1979. The attached listing of nuclear plants, which have received some of this motor control equipment, represents a preliminary check of shipment records. This listing, however, may not be complete.

Gould, Inc., will recall uninstalled items for retrofit and has retrofit kits available for field installation.

Based on the above, licensees are advised to verify all motor starter and contactor shipments received from Gould, Inc., between June 1, 1978 and August 30, 1979, and assure that applicable model and serial number components are corrected by retrofit and subsequent electrical operation tests.

No written response to this Circular is required.

If you desire additional information regarding this matter, contact the Director of the appropriate NRC Regional Office.

1540 191

DUPLICATE DOCUMENT

Entire document previously
entered into system under:

ANO

7910250496

No. of pages:

5