

BUCYRUS-ERIE COMPANY / SOUTH MILWAUKEE, WISCONSIN 53172 / (414) 768-4000

May 17, 1982

U. S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Attention Mr. D. G. Wiedeman
Acting Chief
Materials Radiation Protection

Gentlemen:


This refers to your notice of violation dated May 14, 1982, concerning pocket dosimeter checks.

A statement concerning pocket dosimeter checks was included in the Bucyrus-Erie application for license renewal dated 11-25-81 and was revised on 3-19-82 per your request dated 1-27-82 (attached). The dosimeter check had not been part of our procedures prior to the license renewal application and was not performed in 1981.

On 5-12-82, a pocket dosimeter check was performed (attached) according to the procedure outlined in our application pending approval. The results indicated that the dosimeters were responding to radiation within the limits specified in 10 CFR 34.33(c). Pending your approval of our license application, the dosimeter check procedure will become a part of our operating and emergency procedures and will be performed according to 10 CFR 34.33(c).

Sincerely,

BUCYRUS-ERIE COMPANY


John M. Mertz
Radiography Supervisor

lcp