



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

TIC
50-400
401
402
403

In Reply Refer To:
RII:JPO
50-325, 50-324
50-400, 50-401
50-402, 50-403
50-261

SEP 7 1979


Carolina Power and Light Company
ATTN: J. A. Jones
Executive Vice President
and Chief Operating Officer
411 Fayetteville Street
Raleigh, NC 27602

Gentlemen:

With this Information Notice the Nuclear Regulatory Commission is extending an existing mechanism previously used for informing facility licensees of significant operating events to include informing operator licensees of significant events which could impact on conditions of their NRC licenses. This Information Notice is being reissued to correct a word omission and a punctuation error that, when taken together, completely changed the intent of a statement. The changed statement is underlined in the text of the Information Notice.

It is requested that the facility licensee provide copies of this Information Notice to all NRC licensed individuals at the facility. No specific response is requested at this time. If you have questions regarding this matter please contact the Director of the appropriate NRC Regional Office.

Sincerely,


James P. O'Reilly
Director

Enclosures:

1. IE Information Notice
No. 79-20, Revision 1
2. List of IE Information Notices
Issued in Last Six Months

993224

7909240360

Carolina Power and
Light Company

-2-

cc w/encl:

A. C. Tollison, Jr.

Plant Manager

Box 458

Southport, North Carolina 28461

R. Parsons, Site Manager

Post Office Box 101

New Hill, North Carolina 27562

R. B. Starkey, Jr., Plant Manager

Post Office Box 790

Hartsville, South Carolina 29550

993225

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20555

September 7, 1979

IE Information Notice No. 79-20 Rev. 1

NRC ENFORCEMENT POLICY - NRC LICENSED INDIVIDUALS

Background:

In the past, NRC licensed individuals have been cited by the NRC for failure to comply with the conditions of their licenses. These items of noncompliance can generally be characterized as serious or repeated failures to follow reactor operating procedures. Two recent events involving the radiation overexposure of NRC licensed individuals through their violation of utility procedures, facility Technical Specifications and the Code of Federal Regulations have raised questions about the exercise of their responsibilities.

The purpose of this Information Notice is two-fold:

- (1) To remind the NRC licensed individuals of their responsibilities, not only in the proper operation of the facility controls, but in compliance with the facility administrative procedures, and
- (2) To summarize the enforcement sanctions available to the NRC for use against licensed individuals.

Description of Circumstances:

1. Responsibilities

Facility licensees are charged with the responsibility to design, construct and operate their plants in accordance with NRC requirements to assure that public health and safety are protected. The role of NRC licensed individuals is no less important in the overall Regulatory scheme. The NRC recognizes that timely actions by NRC licensed individuals are an important part of safety. Reliance on these actions is a part of the defense-in-depth concept. Specifically, the NRC requires that:

- (1) Only licensed operators are permitted to perform actions that directly affect reactivity (10 CFR 50.54)
- (2) Licensed operators are required to be present at the controls at all times during the operation of the reactor

DUPLICATE DOCUMENT

993226

Entire document previously entered into system under:

ANO 7908220108

No. of pages: 5