



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION II  
101 MARIETTA ST., N.W., SUITE 3100  
ATLANTA, GEORGIA 30303

TK  
50-413  
414

SEP 7 1979

In Reply Refer To:

RII:JPO

50-413, 50-414

50-491, 50-492

50-493, 50-488

50-489, 50-490

Duke Power Company  
ATTN: L. C. Dail, Vice President  
Design Engineering  
P. O. Box 33189  
Charlotte, NC 28242

Gentlemen:

With this Information Notice the Nuclear Regulatory Commission is extending an existing mechanism previously used for informing facility licensees of significant operating events to include informing operator licensees of significant events which could impact on conditions of their NRC licenses. This Information Notice is being reissued to correct a word omission and a punctuation error that, when taken together, completely changed the intent of a statement. The changed statement is underlined in the text of the Information Notice.

It is requested that the facility licensee provide copies of this Information Notice to all NRC licensed individuals at the facility. No specific response is requested at this time. If you have questions regarding this matter please contact the Director of the appropriate NRC Regional Office.

Sincerely,

James P. O'Reilly  
Director

Enclosures:

1. IE Information Notice  
No. 79-20, Revision 1
2. List of IE Information Notices  
Issued in Last Six Months

993233

790924 0371

Duke Power Company

-2-

cc w/encl:

D. G. Beam, Project Manager  
Post Office Box 223  
Clover, South Carolina 29710

J. T. Moore, Project Manager  
Post Office Box 422  
Gaffney, South Carolina 29340

993234

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

September 7, 1979

IE Information Notice No. 79-20 Rev. 1

NRC ENFORCEMENT POLICY - NRC LICENSED INDIVIDUALS

Background:

In the past, NRC licensed individuals have been cited by the NRC for failure to comply with the conditions of their licenses. These items of noncompliance can generally be characterized as serious or repeated failures to follow reactor operating procedures. Two recent events involving the radiation overexposure of NRC licensed individuals through their violation of utility procedures, facility Technical Specifications and the Code of Federal Regulations have raised questions about the exercise of their responsibilities.

The purpose of this Information Notice is two-fold:

- (1) To remind the NRC licensed individuals of their responsibilities, not only in the proper operation of the facility controls, but in compliance with the facility administrative procedures, and
- (2) To summarize the enforcement sanctions available to the NRC for use against licensed individuals.

Description of Circumstances:

1. Responsibilities

Facility licensees are charged with the responsibility to design, construct and operate their plants in accordance with NRC requirements to assure that public health and safety are protected. The role of NRC licensed individuals is no less important in the overall Regulatory scheme. The NRC recognizes that timely actions by NRC licensed individuals are an important part of safety. Reliance on these actions is a part of the defense-in-depth concept. Specifically, the NRC requires that:

(1) Only licensed operators are permitted to manipulate the controls that directly affect reactivity (10 C

(2) Licensed operators are required times during the operation of th

DUPLICATE DOCUMENT

993235

Entire document previously entered into system under:

ANO 7908220108

No. of pages: 5