

APPENDIX A

NOTICE OF VIOLATION

Duke Power Company  
McGuire Nuclear Station, Unit No. 2

License No. CPPR-84

Based on the NRC inspection August 10, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by 10 CFR 50, Appendix B, Criterion V, and as implemented by DPC Topical Report, paragraph 17.1.5, activities affecting quality shall be prescribed by documented instructions, procedures and drawings...and shall be accomplished in accordance with these instructions, procedures or drawings. DPC Procedure P-1 requires in paragraph 4.1 that prior to unloading nuclear safety-related material the warehouseman shall notify the QC receiving inspector to perform receiving inspection.

Contrary to the above, a PIA Receiving Inspection Information Report dated July 7, 1978 notes the fact that four instruments were installed prior to receipt inspection.

This is a deficiency.

1209 314

7910250 486