P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 656-6911

PESTIPA MASSICHUSETTS ELECTRON COMPANY ME WAS VATER CORRECTIONS
TO BE BUT AS DESCRIPTION OF THE PROPERTY
RECTION AS DESCRIPTION OF THE PROPERTY.

> October 25, 1979 MP-2- 4173

Mr. Boyce H. Grier Director, Region I Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference:

Facility Operating License No. DPR-65

Docket No. 50-336

Reportable Occurrence RO-50-336/79-30/3L-0, 79-31/3L-0

Dear Mr. Grier:

This letter forwards Licensee Event Reports 79-30/3L-0 and 79-31/3L-0 required to be submitted within thirty days pursuant to Millstone Unit 2 Appendix A Technical Specifications, Section 6.9.1.9.b, conditions leading to operation in a degraded mode permitted by a limiting condition for operation. An additional three copies of each report are enclosed.

Yours truly,

Station Superintendent Millstone Nuclear Power Station

JF0/RB:11m

Attachment:

LER's 79-30/3L-0, 79-31/3L-0

Director, Office of Inspection and Enforcement, Washington,

D.C. (30)

Director, Office of Management Information and Program

Control, Washington, D.C. (3)

1281 601

7911010395