

POWER AUTHORITY OF THE STATE OF NEW YORK
JAMES A. FITZPATRICK NUCLEAR POWER PLANT



JOHN D. LEONARD, JR.
Resident Manager

November 13, 1979
JAFP-79-631

P.O. BOX 41
Lycoming, New York 13093
315-342-3840

Mr. Boyce H. Grier
United States Nuclear Regulatory Commission
Region 1
631 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: Docket No. 50-333 Licensee Event Report: 79-089/01T-0

Dear Mr. Grier:

We have enclosed the referenced Licensee Event Report in accordance with Section 6.0 of Technical Specifications and USNRC Regulatory Guide 1.16.

If there are any questions concerning this report, please contact Mr. W. Verne Childs at 315-342-3840, Extension 207.

Very truly yours,

John D. Leonard, Jr.
Resident Manager

JDL:VC:jnk
Enclosure

CC: USNRC Director, Office of Inspection & Enforcement (30 copies)
USNRC Director, Office of Management Information & Program Control (3 copies)
Internal Power Authority Distribution

1347 013

7911160 493
5

POWER AUTHORITY OF THE STATE OF NEW YORK

JAMES A. FITZPATRICK NUCLEAR POWER PLANT

DOCKET NO. 50-333

ATTACHMENT TO LER 79-089/01T-0

Page 1 of 1

The Architect-Engineer notified the Plant Staff that three supports, H11-8 in the Standby Liquid Control (SLC) System, H66-33 in the Containment Vent and Purge System, and H76-61 in the Fire Protection System, were inoperable based upon the criterion of the 14 August 1979 letter lifting the Show Cause Order of 13 March 1979. In accordance with the 14 August 1979 letter, analysis was performed with these supports removed from the system. This analysis showed the SLC and Fire Protection Systems to remain operable. Those portions of the containment vent and purge system piping associated with H66-33 remained inoperable. Modifications to H66-33 were completed within the seven day time period required by the 14 August 1979 letter and the event did not represent a significant hazard to the public health and safety.

134Z 014