License No. DPR-50

APPENDIX A

NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted on November 17-21, 1975, it appears that certain of your activities were not conducted in full compliance with conditions of your license as indicated below:

A. Contrary to the requirement of Technical Specification 6.1.i.2.b.6 the corporate technical staff review of a violation of technical specification 4.1.3 was not conducted.

This is an infraction.

B. Contrary to the requirement of technical specification 6.1.i.1.d.7 a PORC review of violations of technical specifications was not conducted for Items of Noncompliance from Region I Inspection Report 50-289/75-16 and 75-21.

This item is a deficiency.

Other infractions and deficiencies identified through your internal audit program and which were reported in a timely manner and corrected, or corrective action was initiated, are set out in the inspection report. No additional information is needed for these items at this time.

7910190

1451 251