U. S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT REGION IV

LE Inspection Report No. 50-445/79-21 Docket No. 50-445 Texas Utilities Generating Company Licensee: 2001 Bryan Tower Dallas, Texas 75201 Facility: Comanche Peak Electric Station - Unit 1 Inspection At: Glen Rose, Texas Inspection Conducted: August 29, 1979 Principal Inspector: Other Accompanying Personnel: Taylor, Resident Reactor Inspector In R. G. Spangler, Reactor Inspector 7. ... Westerman, Chief, Reactor Projects Section G. L. Madsen, Chief, Reactor Operations and Nuclear Support Branch 7. 2. Wester Reviewed By:

T. F. Westerman, Chief, Reactor Projects Section

227 317

Inspection Summary

Inspection on August 29, 1979 (Report No. 50-445/79-21)

Area Inspected: This inspection consisted of the second corporate management meeting. The meeting involved discussions by both NRC and the licensee regarding preoperational organization and testing activities. The inspection involved fifteen (15) hours on-site time by six NRC inspectors.

1227 318

DETAILS

1. Management Meeting

The second corporate management meeting between the NRC Region IV staff and the Texas Utilities Generating Company staff was conducted at the licensee's offices at Comanche Peak Nuclear Generating Station on August 29, 1979. The following licensee personnel were in attendance.

Texas Utilities Generating Company

- B. R. Clements, Vice President and Manager, Nuclear Operations
- J. C. Kuykendall, General Superintendent
- D. N. Chapman, Manager, Quality Assurance
- R. A. Jones, Assistant General Superintendent
- D. W. Braswell, Engineering Superintendent
- R. B. Seidel, Operations Superintendent
- T. L. Thompson, Maintenance Superintendent
- R. Camp, Lead Startup Engineer

Westinghouse Electric Corporation

P. S. Vanteslaar, Site Manager

NRC Region IV Office of Inspection & Enforcement

- G. L. Madsen, Chief, Reactor Operations & Nuclear Support Branch
- T. F. Westerman, Chief, Reactor Projects Section
- B. Murray, Radiation Specialist
- R. Smith, Operations Reactor Inspector
- R. G. Spangler, Operations Reactor Inspector
- R. G. Taylor, Construction Regional Resident Inspector

Purpose and Scope of the Meeting

A meeting was held with management representatives of the licensee and NSSS Site Manager to (1) review the status of construction related problems; (2) identify the change in emphasis of the inspection program; (3) to clarify the licensee's program for staffing the facility during the preoperational and startup testing phases; (4) to determine the quality assurance requirements which would be applicable during the testing phases; and (5) to advise the licensee of the programmatic requirements of the inspection program for the testing phases.

3. Items Discussed During the Meeting

The general areas outlined below were discussed by the licensee representatives and/or the Region IV personnel. Questions which were raised during the course of the meeting were discussed and resolved during the meeting.

- a. Construction problems which are still unresolved and the remaining construction inspection effort.
- b. Staffing of the facility during preoperational and startup testing.
- c. Status of the preoperational testing program.

* 5 st ..

- d. Quality Assurance program to be used to implement the 10 CFR 50, Appendix B criteria.
- e. Provisions of the FSAR that IE will inspect against with respect to the licensee's preparation and conduct of testing and operations.
- f. The IE program for selective review of test program elements and licensee activities.
- The IE program for inspections against the Technical Specifications and 10 CFR 50.59 after the operating license is issued.
- h. The der the for the completion of various stages of the testing program

1227 320