



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION V  
1990 N. CALIFORNIA BOULEVARD  
SUITE 202, WALNUT CREEK PLAZA  
WALNUT CREEK, CALIFORNIA 94596

TERA

OCT 20 1979

Docket Nos. 50-460  
50-513

Washington Public Power Supply System  
P. O. Box 968  
Richland, Washington 99352

Attention: Mr. N. O. Strand  
Managing Director

Gentlemen:

Subject: Report on Deficiency Involving ECCS Make-up Pump Speed  
Increaser Supports, WNP Nos. 1 & 4 (Your Letter of  
October 18, 1979)

Thank you for your letter, referenced above, which forwarded a report  
pursuant to 10 CFR 50.55(e) regarding the subject matter.

Your report will be reviewed and evaluated and should we require additional  
information concerning this matter, we will contact you.

Your cooperation with us is appreciated.

Sincerely,

A handwritten signature in cursive script, appearing to read "R. H. Engelken".


R. H. Engelken  
Director

1333 191

S

7911150

020



Washington Public Power Supply System  
A JOINT OPERATING AGENCY

P. O. Box 968 3000 GEO. WASHINGTON WAY RICHLAND, WASHINGTON 99352 PHONE (509) 375-5000

October 18, 1979  
G01-79-533



Nuclear Regulatory Commission  
Region V  
Suite 202 Walnut Creek Plaza  
1900 N. California Boulevard  
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Subject: WPPSS Nuclear Projects Nos. 1/4  
Docket Nos. 50-460 and 50-513  
Reportable Condition 10CFR50.55(e)  
Emergency Core Cooling Make-Up Pump  
Speed In increaser Supports

Dear Mr. Engelken:

Mr. Al Toth, US NRC Region V Resident Inspector, was verbally notified of this reportable condition on October 1, 1979, by the Supply System.

Appendix A to this letter contains the WPPSS final report on the subject condition.

If you have any questions or desire further information, please advise.

Very truly yours,

D. L. Renberger  
Assistant Director-Technology

Attachment  
jds

cc: CR Bryant - BPA  
BD Redd - UE&C, Phil.  
JG Davis NRC Region 1

1333 192

DUPLICATE  
7910240576

79-64