



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

tic

Docket No. 50-346

OCT 25 1979

Toledo Edison Company
ATTN: Mr. Richard P. Crouse
Vice President - Energy
Supply
Edison Plaza
300 Madison Avenue
Toledo, OH 43652

Gentlemen:

This refers to my immediate action letter to you dated October 17, 1979, and to the equipment problems listed therein.

The NRC onsite inspectors have reviewed your determination of the causes of failure and the corrective actions you have taken to prevent recurrence. The onsite team members have also inspected the equipment; observed the failed components; and observed repairs, modification, and testing of the components and equipment.

The details of our inspection findings will be contained in the inspection report to be issued as a result of this review.

We have no further questions at this time concerning these items.

Sincerely,

James G. Keppler
James G. Keppler
Director

cc: Mr. T. D. Murray, Station
Superintendent
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Harold W. Kohn, Power
Siting Commission
Helen W. Evans, State of Ohio

1375 282

7911210 040

Q